



An Investment Casting Institute Publication

Atlas of Casting Defects

| | |
|-----------------------------------|-----------|
| Introduction | 3 |
| Positive Defect Identifier | 4 |
| Negative Defect Identifier | 6 |
| List of Defects | 60 |

December 2017

Page intentionally left blank



An Investment Casting Institute Publication

The Atlas of Casting Defects was updated and reformatted based on feedback from our members. This restructured Atlas combines the previous versions of the Atlas of Shell Defects and the Atlas of Casting Defects into a single publication. We have addressed all the potential causes of a casting defect broken down by Wax, Shell or Foundry. In addition, there is a new tool, the Defect Identifier, which can assist in pinpointing a particular defect. The only defects which are not included in this Atlas are wax defects that should be caught and corrected in the wax department. These defects are still covered in the Atlas of Wax Pattern Defects publication.

The ICI has also launched an on-line version of this publication which provides increased ease and flexibility thus reducing the time necessary to identify and resolve casting defects.

Acknowledgments

The Investment Casting Institute wishes to thank all of the members of the Institute's Publication Committee who provided information, photographs and valuable resources. The individuals on this committee worked hard to create this Atlas of Casting Defects. Without their support, time and effort, we would not be able to provide this valuable updated publication.

Publications Committee

Chairman

Julie Markee
Key Process Innovations, LLC

Members

Russ Gallagher
Bescast, Inc.

Noor Alam
DePuy

Erin Almaleh
Investment Casting Institute

Matt Cavins
O'Fallon Castings

Tim Sullivan
Hitchiner, Inc.

Naum Cherepakhov
Industry Retiree

Barry Dahlin
Westech Products

Wayne Gayford
DePuy

Manuel Guerra
Remet


Mike Hendricks
Ransom & Randolph

Mark Oles
Pine Tree Castings


Chris O'Rourke
DePuy

Al Torok
*Yamaha Marine
Precision Propellers*

Defect Identifier: Positive




Defect Identifier: Positive




The information pertaining to this defect is available as part of the Wax Atlas. The Wax Atlas can be accessed at www.investmentcasting.org or ordered by contacting (201) 573-9770

Defect Identifier: Negative





Defect Identifier: Negative



The information pertaining to this defect is available as part of the Wax Atlas. The Wax Atlas can be accessed at www.investmentcasting.org or ordered by contacting (201) 573-9770

Bubbles



Mechanism

Air trapped against the wax pattern by the primary slurry layer

Description

Defect Type

Positive

Appearance

Small, smooth spherical, oval or elongated tubular shaped positive

Size

1/8" or less

Typical Location

Difficult to wet out areas during shell building

Similar to

Wax bubbles (see Atlas of Wax Pattern Defects), [Stuck Shot](#)

Aliases



BBs, Air Bubble

Method for defect determination

Visible to eye. Smooth surface of defect

| Area | Possible Cause | Potential Correction |
|-------|------------------------------|---|
| Wax | Bad mold design | Re-orient the part to prevent air from being trapped during dipping |
| Shell | Poor dipping technique | Immerse the pattern slowly in the slurry, use vibration or, compressed air or vacuum to pop any trapped air bubbles |
| Shell | Poor draining technique | Back drain slurry into areas that cannot be wet out during dipping |
| Shell | Incomplete pattern wetting | Use a pre-wet or use a lower prime coat viscosity |
| Shell | Insufficient slurry wetting | Insure the correct amount of wetting agent is in the slurry |
| Shell | Incomplete pattern cleaning | Insure the silicone is removed from all surfaces of the patterns and no air bubbles are preventing proper cleaning |
| Shell | High air level in the slurry | Insure air is not being sucked into the slurry by the mixer. Conduct antifoam test and adjust if necessary |

Buckle



Mechanism

The bond strength of the primary layer to the wax patten is insufficient and the primary layer buckles (lifts) off the pattern. The bond strength can be insufficient for a number of reasons including stress on the primary layer as it shrinks during drying.

Description

Defect Type

Positive

Appearance

Faceted or pyramid like surface with a distinct ridgeline often associated with flash

Typical Location

Flat featureless surfaces

Similar to

Prime coat lift

Method for defect determination

When a shell buckles, it only separates from the pattern. With prime coat lift, the shell also fractures, allowing the backup layers to fill the gap between the primary layer and the wax pattern

| Area | Possible Cause | Potential Correction |
|-------|---|---|
| Wax | Temperature change in wax causes the wax to move and disrupt the primary layer bond. Wax pattern temperature not stable | Ensure the wax pattern has stabilized in temperature before applying shell layers |
| Wax | Pattern cleaning inadequate. Poor adhesion of the primary coat to the wax pattern | Increase etch strength or, time in etch. Reduce the time from etch to primary layer |
| Wax | Pattern flexing during dipping | Add additional pattern supports |
| Shell | Large temperature change | Control the dipping area to +/- 3 F |
| Shell | Drying too long | Set a maximum dry time |
| Shell | Drying too short | Insure the primary layer is completely dry before applying backup layers |
| Shell | Poor prime coat wetting | Confirm the prime slurry is wetting the pattern |

continued on next page




continued from previous page



| Area | Possible Cause | Potential Correction |
|---------------------|--|---|
| Shell | Low adhesion binder | Increase polymer level |
| Shell | Drying too fast (high pattern shrinkage & drying stress) | Slow down (Increase) the drying by reducing airflow or increasing room humidity or reduce airflow |
| Shell | Pre-wet is lifting prime | Eliminate pre-wet or reduce dry time between pre-wet and slurry application |
| Shell | Too much slurry on interior surfaces | Decrease slurry viscosity or increase drain time |
| Shell | Too little slurry on interior surfaces | Increase slurry viscosity or decrease drain time |
| Shell | Insufficient stucco on interior surfaces | Don't let slurry surface dry or over drain before stucco application |
| Shell | Primary slurry in poor condition | Employ proper slurry controls |
| Shell | Soaking (saturating) the mold promotes lifting. Vibration too high | Vibration used during dipping can cause the primary coat to separate from the pattern |
| Shell | Pattern flexing during dipping | Add additional pattern supports |
| Shell | Soaking (saturating) the mold promotes lifting | Stucco molds immediately after slurry has drained |
| Shell | Thermal expansion mismatches within the shell | Change shell composition |
| Other (Mold design) | Pattern is too flat and featureless | Add ribs or dimples to break up flatness and create features |
| Other | Pattern flexing during dipping | Add additional pattern supports |

Bulge



Mechanism

Permanent deflection of the mold wall either during dewaxing or casting.

Description

Defect Type

Positive

Appearance

Gradual thickening of the casting wall. May have finning in the area of the bulge. May not be detectable by the naked eye but can be caught by gauging.

Typical Location

Parallel surfaces, deep holes, or slots. Adjacent patterns on assembly. Large flat featureless surfaces

Similar to

Similar in appearance to shell [buckle](#) but it doesn't have the definitive shape of a crack in the casting.

Aliases

Bulging, bulging cracking, bulging overheating, shell bulge

Method for defect determination

Shell bulge generally has a more rounded surface

| Area | Possible Cause | Potential Correction |
|-------|--|---|
| Wax | Patterns too close causing premature bridging | Use spacers during assembly to produce consistent pattern spacing |
| Shell | Shell too thin | Add shell layers or add stiffening feature |
| Shell | Mold hot strength too low (mold creeping during casting cooling) | 1) Increase refractoriness of the shell 2) Ensure optimal SiO ₂ levels in the backup slurry 3) Ensure uniform mold thickness |
| Shell | Slurry not wetting out area | 1) Use vacuum dipping or re-orient pattern. 2) Use a thinner slurry |
| Shell | Slurry/stucco not getting into area | Use a "poured core" |
| Shell | Stucco not getting into area | 1) Rainfall, hand pour or re-orient pattern 2) If bridging in slots or holes, use a finer stucco or make sure hole is open prior to applying subsequent dips until sufficient slurry/stucco has been applied |

continued on next page

Bulge





continued from previous page

| Area | Possible Cause | Potential Correction |
|---------|---|--|
| Shell | Slurry is being washed away when subsequent coats are applied | Ensure sufficient intra-coat dry time and conditions for hard to dry areas of the mold |
| Shell | Green strength of the shell is too low to withstand dewaxing | <ol style="list-style-type: none"> 1) Increase the dry time between each layer 2) Apply additional coats 3) Increase final dry time 4) Redesign assembly to permit a more rapid heat transfer to all parts of mold 5) Vent pattern cavities 6) Check dewax process for optimal performance and that it is in control |
| Shell | Deformation during dewaxing | See " Finning " |
| Foundry | Solidification time too long | Decrease metal temperature, decrease mold temperature, speed casting cooling rate |
| Foundry | Ferrosstatic pressure too high | Reduce vacuum level, reduce spinning rate (centrifugal) |
| Foundry | Ferrosstatic pressure too high | Reduce the metal height above the part |



Cold Shut



Mechanism

Incomplete joining of two metal fronts

Description

Defect Type
Negative

Appearance

Smooth, linear, shallow, rounded edged impression extending into feature wall. This defect takes the form of a crack or discontinuity in the surface with rounded edges indicating the freezing or solidification of two or more streams of metal before they had time to completely fuse together.

Size

varies

Typical Location

Thin sections or areas furthest away from gate where two metal fronts meet.

Similar to

Wax knitline (see Atlas of Wax Pattern Defects)

Aliases

Cold Shot, Short Fill



Method for defect determination

Penetrant inspection, visual inspection, metallographic inspection for evidence of non-bonding along line below cast surface. A wax knit line will have not extend below cast surface ceramic in the junction.

| Area | Possible Cause | Potential Correction |
|---------|--|--|
| Foundry | Metal not hot enough | Increase metal superheat |
| Foundry | Mold not hot enough | Increase mold temperature/increase or add mold insulation |
| Foundry | For air cast, mold not permeable resulting in backpressure/trapping air that slows metal fill time | Reduce shell thickness or gating design to fill pattern cavity from more locations. Add vents. Increase shell permeability |
| Foundry | Poor metal fluidity | Consider modifications to alloy composition |
| Foundry | Slow metal pour rate | Increase pour rate |
| Foundry | Interrupted pour | Maintain a steady pour rate until mold is full |



Core Breakage



Mechanism

Core breaks either during wax injection, during mold heating, or metal pouring

Description

Defect Type
Negative

Appearance

Metal fin across an area that is formed by a ceramic core. In the case of core break and shift, missing metal where a wall should be.

Size
varies


Typical Location

Can only occur on casting made with ceramic core

Method for defect determination

Visual, X-ray in case of hidden from view

| Area | Possible Cause | Potential Correction |
|---------------------|---|--|
| Wax | Mold design creates stress on core upon clamping or wax injection | Examine need for core print relief or core supports to reduce stress |
| Shell | Poor core slipping method | Examine for too many core locks or "prints" |
| Other (Mold design) | Too high of wax injection pressure | Reduce injection pressure |





Mechanism

Typically, internal stresses from solid-state cooling or rapid cooling can cause cracking.

Description

Defect Type

Negative

Appearance

Jagged crack with irregular path

Typical Location

Geometry involves seriously restrained contraction or in a local volume of unfed metal. May occur at the intersection of thick and thin section.

Similar to

[Hot Tear](#)

Method for defect determination

Visual inspection and Penetrant inspection typically reveal cracks. Cracks form roughly 90° to stress direction.


| Area | Possible Cause | Potential Correction |
|-----------------------------|--|---|
| Wax | Major sectional changes in the casting design | Modify gating to prevent strong gates or runners from preventing the casting from contracting |
| Wax | Restriction of casting contraction at elevated temperature | Modify the design to avoid contraction restriction and strengthen the weak areas by the use of webs |
| Foundry | Premature movement of mold after casting | Allow time for the casting to solidify before moving |
| Other (Post-cast operation) | Uneven cooling rate -The use of water to cool a hot casting can set up high internal stress | Avoid rapid cooling methods |
| Other (Post-cast machining) | Removal of cast material can create an imbalance of the internal stress leading to cracking. | Add a stress-relief thermal cycle to as-cast part prior to metal removal operations |
| Other (Casting design) | Restriction of casting contraction at elevated temperature | Modify the design to avoid contraction restriction and strengthen the weak areas by the use of webs |

continued on next page





continued from previous page

| Area | Possible Cause | Potential Correction |
|------------------------|---|---|
| Other (Casting design) | Major sectional changes in the casting design | Modify gating to prevent strong gates or runners from preventing the casting from contracting |
| Other (Casting design) | Sharp internal angles | Ensure adequate fillet radii |



Cut-off Damage



Mechanism

Blade or plasma torch deflects into casting or continues into casting after cut

Description

Defect Type

Negative

Appearance

Slot or beveled face with characteristic grooves running the direction of the cut-off wheel

Typical Location



Anywhere but typically near a gate contact

Method for defect determination

Visual inspection

| Area | Possible Cause | Potential Correction |
|-----------------------------|--|--|
| Other (Gating Design) | Castings too close to the runner bar/ variable distance from runner bar | Increase gate length |
| Other (Post-Cast operation) | Incorrect part loading in cutoff fixture | Mistake proof the holding fixture |
| Other (Post-Cast operation) | Cut-off blade flex during the cut-off | Use different blade, change gate shape |

Delamination



Mechanism

Failure of bond between 1st and 2nd layer of shell. The first layer is pushed or pulled into the mold cavity usually during dewax. Sometimes the shell cracks and metal fills the gap between the layers producing a scab.

Description

Defect Type

Negative

Appearance

Faceted metal indentation sometimes accompanied by a positive metal scab

Typical Location

Flat featureless surfaces

Aliases

Scabbing, Reverse Buckle

Method for defect determination



Visual, appears as scab with indentation under scab

| Area | Possible Cause | Potential Correction |
|-------|---|---|
| Shell | Incomplete wetting between 1st and 2nd layer | Blow off loose primary coat stucco. Ensure immersion time in 2nd layer slurry is adequate to wet-out the primary layer |
| Shell | Etch too strong – too tacky | Reduce etch strength or time |
| Shell | Drying rate of 2nd layer too high | Increase drying room humidity |
| Shell | Poor bond between prime and backup layer | Ensure adequate keying between the primary and first backup coat. Use a coarser or more angular primary coat stucco blow off loose or excess stucco |
| Shell | Moisture trapped behind the primary coat | Ensure adequate drying of the mold prior to dewaxing |
| Shell | Differential expansion stresses between the primary and secondary coats | Ensure the thermal expansion of the primary coat is compatible with that of the shell coats |
| Shell | Rapid pressure release during autoclave dewaxing | Autoclave blowdown should be gradual and take 2 minutes or more |

continued on next page

Delamination

Additional
examples



Distortion




Figure 1
Raised pads are witness to gating locations on the outside of the tube casting.

Figure 2
Depressions on the interior of the tube are created during the casting process.

Mechanism

Distortion of the casting occurring at wax injection, pattern assembly, or casting cooling.

Description

Defect Type

Shape

Appearance

The geometry does not conform to the drawing

Size

varies

Typical Location

Opposite gate locations

Similar to

[Sink](#), Cavitation (See Atlas of Wax Pattern Defects)

Method for defect determination

Visual inspections and customary dimensional inspection tools

| Area | Possible Cause | Potential Correction |
|------------------------|--|---|
| Other (Casting design) | Geometry of the casting and or running system causing uneven contraction | Minimize uneven stresses that develop with solid-state metal contraction occurs |
| Other (Mold design) | Improper gating system design | Design the gating and runner system to prevent uneven stresses |
| Other (Mold design) | Ingates contracting and pulling part of the casting | Examine the runner system and modify to reduce stresses |
| Wax | Improper wax pattern handling ejected from die | Modify release agent spraying technique, frequency. Add ejector pins |
| Wax | Improper wax pattern storage | Store patterns in a manner to prevent distortion |
| Wax | Ingates contracting and pulling part of the casting | Examine the runner system and modify to reduce stresses |
| Wax | Improper gating system design | Design the gating and runner system to prevent distortion |

continued on next page



continued from previous page

| Area | Possible Cause | Potential Correction |
|------------------------|--|---|
| Shell | High strength mold preventing even contraction | Reduce the mold strength |
| Other | Knockout conducted at too high a temperature | Knockout at a lower temperature |
| Foundry | Improper casting handling | Ensure cast molds are handled with care – especially at high temperature |
| Other (Heat treatment) | Stresses induced during heat treatment | Ensure the castings are correctly supported during heat treatment. Use the slowest quenching method that will achieve the required hardness |

Etch Spotting



Mechanism

During pattern cleaning prior to shell building, the etch solution is not completely rinsed off. The etch continues to attack the wax forming rings or drips on the bottom of the pattern

Description

Defect Type

Negative and Positive

Appearance

Smooth. Raised droplet or “coffee ring” like appearance where ring may be slightly indented into casting

Special Circumstances

Most common with difficult to rinse etch solutions

Size

1/4” or less

Typical Location

End of part away from the pour cup. Areas where etch rinse water beads up after pattern cleaning or there is insufficient rinse action on the surface of wax. Often in deep corners but can occur on open surfaces.

Aliases

Fisheyes

Method for defect determination

Monitor the etching operation and inspect wax patterns prior to first dip in pre-wet or primary dip

| Area | Possible Cause | Potential Correction |
|-------|-------------------------------------|--|
| Shell | Incomplete rinse after pattern etch | Increase agitation during rinse, keep rinse water clean and/or use multiple rinse tanks. Last rinse water should always be clear to ensure cleanliness. Make sure water temperature is room temperature. |
| Shell | Incorrect etch concentration | Some etch products require mixing with water prior to use. Verify measurements and test concentration if possible. |

Excess Metal



Mechanism

Thin or weak areas of the shell fail during dewax or casting allowing metal to leak into the void in the shell.

Description

Defect Type

Positive

Appearance

Irregular shaped mass typically attached to the casting by flash

Size

Varies but typically metal is restrained by external shell geometry

Typical Location

Holes, slots, or tight corners

Aliases

Metal breakthrough,
Metal Penetration,
Core Collapse

Method for defect determination

Visual Inspection


| Area | Possible Cause | Potential Correction |
|---------------------|---|---|
| Other (Mold design) | Poor mold design | Re-orient the part to improve slurry and stucco coverage |
| Shell | Poor shell build / slurry / stucco schedule | Improve wetting of detail by shell code changes, re-orienting the part or vacuum dipping, thinner slurries and finer stuccos, use intermediate slurry and or stucco |
| Shell | Incomplete loose stucco removal | Blow loose stucco out of detail, slots or blind holes |
| Shell | Incomplete slurry wetting | Change pattern orientation, use vacuum dipping, lower the slurry viscosity or use prewet solutions |
| Shell | Incomplete drying | Increase the dry time between layers |
| Shell | Incomplete stucco coverage | Pour stucco into the area, change orientation of the pattern, use finer or intermediate stucco |
| Shell | Stucco too large | Change shell code, use finer stucco |



continued on next page



continued from previous page

| Area | Possible Cause | Potential Correction |
|------------------------|--|---|
| Shell | Stucco contains large particles ("rice krispies" or "snerds") | Sift the large particles out of the stucco |
| Shell | Dewax cracking | Improve dewax performance |
| Shell | Autoclave depressurization too rapid | Gradually depressurize the autoclave over 2 minutes or more |
| Other (Casting design) | The core length to cross-sectional area too great to allow production of a sound core by normal shell techniques | Form area with "poured core" or preformed ceramic core |





Mechanism

Shell crack during shell building, drying or dewaxing, and molten metal fills the crack during casting. Cylindrical shapes are more prone to this defect due to hoop stress

Description

Defect Type

Positive

Appearance

Sharp, linear fin of metal perpendicular to the surface

Typical Location

Flat featureless surfaces, sharp edges or cylindrical parts, across holes

Similar to

Wax flash (See Atlas of Wax Pattern Defects)

Aliases

Flash,
Shell Crack,
Mold Crack

Method for defect determination

Wax flash can only be located on the parting line of the pattern


| Area | Possible Cause | Potential Correction |
|-------|---|--|
| Wax | Runner wax melts too slow creating increased pressure by part wax on mold as it melts | Change the formulation of the runner wax to insure it melts as fast or faster than the pattern wax, use a low melting point wax to apply "dip seal" to the runner system |
| Wax | Pattern wax does not bleed through the mold during dewaxing | Change pattern wax or increase green permeability |
| Wax | Wax flash / parting line not removed | Removal all parting line indications |
| Shell | Low mold strength | Add an additional shell layer, use a polymer, increase SiO ₂ of slurry |
| Shell | Incomplete mold drying | Increase the mold dry time |
| Shell | Slow autoclave pressurization | The autoclave should rapidly pressurize to 80 psi in 10 seconds or less |
| Shell | Large temperature fluctuations during drying | Maintain 3F maximum temperature variation |

continued on next page



continued from previous page

| Area | Possible Cause | Potential Correction |
|-------------|---|---|
| Shell | Inadequate dewax pressure relief | Add venting to difficult to dewax areas |
| Shell | Slow dewax loading | Load dewax unit quickly to reduce mold exposure to heat |
| Shell | Pattern wax does not bleed through the mold during dewaxing | Change pattern wax or increase the shell permeability |



Mechanism

During casting, turbulent flow mixes the air that is exiting the mold with the metal that is entering. These bubbles float to the surface of the metal but are trapped by the solidifying metal. (Like air bubbles trapped under a layer of ice). This also can be caused by incomplete burnout of the wax and filler material in the mold, igniting when the molten metal reaches this material. Gas defects can also be formed when ceramic cores out-gas, or the strengthening materials (such as binders or superglue) applied to cores, burns out (usually associated with low preheat temperatures). Low permeability of molds is another cause of entrapped gas.

Description

Defect Type

Negative

Appearance

Round smooth walled cavities which may exhibit a slightly oxidized surface of varying diameter

Size

0.5 to 4 mm

continued on next page

| Area | Possible Cause | Potential Correction |
|---------------------|--|--|
| Other (Mold design) | Poor gating design | Add vent at top of part to allow air to escape |
| Other (Mold design) | Poor gating design | Modify gating system to prevent turbulence during metal filling |
| Other (Mold design) | Low ferrostatic pressure | Increase the height of the mold, use vacuum assistance, centrifuge |
| Shell | Low mold permeability | Increase the mold permeability or use vacuum assistance during pouring |
| Foundry | Bad pouring practice | Reduce height from ladle to mold, pour down the side of the pour cup |
| Foundry | Excessively turbulent metal flow into the mold. Low ferrostatic pressure | Modify the gating technique to give less turbulent flow; self-venting mold. Increase the height of the mold, use vacuum assistance, centrifuge |
| Foundry | Low metal temperature | Increasing the metal temperature allows more time for gas bubbles to escape before a skin is formed |

continued on next page

Gas



continued from previous page

Typical Location

Generally located on the upper region of the part as-cast

Similar to

Pinholes, Blowholes, [Slag](#), [Incomplete Burn-out](#)

Aliases

Entrapped Air, Porosity

Method for defect determination



Upper region of the part as-cast, only a few holes. Fewer number of cavities than pinholes

continued from previous page

| Area | Possible Cause | Potential Correction |
|---------|--|---|
| Foundry | Excess wax and Filler material after dewaxing mold | Burn molds out fully prior to preheat. Add excess oxygen to preheat/ burnout oven to ensure complete burnout of mold. |
| Foundry | Poor deoxidation practices | Improve practices |
| Foundry | Moisture contained within the metal feedstock | Ensure metal is free from moisture rust or lubricants. Ensure ladles are cured and dry before use. |



Grinding Damage



Mechanism

Abrasive grinding belt or wheel continues grinding into casting after removing the gate

Description

Defect Type
Negative

Appearance


Missing features or low wall thickness with linear serrations

Typical Location

Near gates or on same surface as gates


Similar to

Cutoff Damage



| Area | Possible Cause | Potential Correction |
|-------|--|---|
| Other | Grind depth set too deep | Ensure grinding depth set correctly on automatic grinder |
| Other | Part improperly loaded | Mistake proof part loading on the grind fixture |
| Other | Residual ceramic prevents proper fixture loading | Improve ceramic removal method |
| Other | Incorrect belt width | The contact wheel and grinding belt should be sized according to the gate width |
| Other | Snagging from loose grip in operator's hand | Hold casting tight in hand when approaching belt or disc |
| Other | Excess Snagging from inability to see grind area interface | Change view angle |
| Other | Incorrect grit size on belt | Ensure belt grit size before grinding |

Handling Damage



Mechanism

Castings are damaged at some point after solidification

Description

Defect Type

Negative and positive

Appearance

Dinged surface. Smooth negative with accompanying positive burr, dented edge, rolled corner, bent or distorted metal

Size

Various

Typical Location

Protruding features, corners, thin areas

Similar to

Wax damage (See Atlas of Wax Pattern Defects)


Aliases

Knockout Damage

Method for defect determination

Visual or dimensional gauging

| Area | Possible Cause | Potential Correction |
|----------------------------------|---|--|
| Foundry | Damage occurring during handling | Prevent operators from dropping castings onto one another |
| Other (Knockout/cutoff/blasting) | Damage occurring during mechanical cleaning | Reduce tumbling speed or add cushioning material with castings (addition of rubber blocks during tumble blast) |
| Other (Transporting) | Damage occurring during transportation | Ensure floors are level, wheels on carts are adequate |



Mechanism

During casting cooling, the strength of the shell or gating system exceeds that of the solidifying metal

Description

Defect Type

Negative

Appearance

Jagged crack with irregular path, typically with an oxidized fracture face

Typical Location

Slow to cool or solidify areas where the geometry involves seriously restrained contraction or in a local volume of unfed metal. May occur at the intersection of thick and thin section.

Similar to

[Crack](#), Wax Crack (See Atlas of Wax Pattern Defects)

Aliases

Shrinkage Crack

Method for defect determination

A wax crack will typically contain refractory and have a somewhat smooth, non-dendritic fracture face

| Area | Possible Cause | Potential Correction |
|---------|--|---|
| Wax | Restriction of casting contraction at elevated temperature | Modify the design to avoid contraction restriction and strengthen the weak areas by the use of webs. |
| Wax | Major sectional changes in the casting design | Modify gating to prevent strong gates or runners from preventing the casting from contracting |
| Shell | Sharp internal angles | Ensure adequate fillet radii |
| Shell | Gating incorrect | Reduce the mold strength. Modify gating to prevent strong gates or runners from preventing the casting from contracting Use a slower cooling rate |
| Shell | Shell too strong | Reduce shell layers. Allow time for the casting to solidify before moving |
| Foundry | Premature movement of mold after casting | Allow time for the casting to solidify before moving |
| Foundry | Uneven cooling rate | Sink mold after casting or wrap in insulation |

continued on next page



continued from previous page

| Area | Possible Cause | Potential Correction |
|------------------------|--|---|
| Foundry | Gating incorrect | Reduce the mold strength. Modify gating to prevent strong gates or runners from preventing the casting from contracting Use a slower cooling rate |
| Foundry | Metal chemistry | Use certified virgin ingots |
| Foundry | Metal chemistry | Modify the metal chemistry |
| Other (Mold design) | Gating incorrect | Reduce the mold strength. Modify gating to prevent strong gates or runners from preventing the casting from contracting Use a slower cooling rate |
| Other (Casting design) | Sharp internal angles | Ensure adequate fillet radii |
| Other (Casting design) | Casting design | Modify the casting design where possible to reduce major sectional changes |
| Other (Mold Design) | Restriction of casting contraction at elevated temperature | Modify the design to avoid contraction restriction and strengthen the weak areas by the use of webs. |
| Other (Casting design) | Major sectional changes in the casting design | Modify gating to prevent strong gates or runners from preventing the casting from contracting |

Incomplete Burn-out



Mechanism

During casting, residual carbon in the mold remaining from incomplete burnout react with molten metal producing CO. The CO, in the form of a gas bubble, prevents the metal from filling the area

Description

Defect Type
Negative

Appearance

Smooth irregular shaped voids generally in or just under the cast surface usually irregular in outline but tending to assume a spherical or wormlike shape. The casting surface may exhibit a matte finish in the area of the defect

Size
1 to 4 mm

Typical Location

Sections of mold that don't drain during dewax. Areas of mold that are densely packed when shell built.


Similar to
[Gas](#), [Slag](#)

Alias
Ash

Method for defect determination

Gas tends to be on the upper surface or the part during casting. Metal mold reaction is located where the carbon does not burn out

| Area | Possible Cause | Potential Correction |
|---------------------|--|--|
| Other (Mold design) | Poor wax drainage | Orient the parts to allow for a high level of wax drainage from the mold |
| Other (Mold design) | Patterns too close | Increase spacing between patterns to prevent shell bridging |
| Wax | Patterns too close | Increase spacing between patterns to prevent shell bridging |
| Wax | High ash content in wax | Use a low ash content wax |
| Shell | Incomplete wax removal | Insure the dewax cycle time is adequate to remove all of the wax |
| Foundry | Short mold burn-out time | Increase burnout time |
| Foundry | Insufficient air circulation in the mold | Place molds on stand or ribbed hearth plate |
| Foundry | Low oxygen level in the burnout furnace | Increase excess air |
| Foundry | Contamination of the mold | Rinse mold and/or cover pour cup to prevent contamination |



Mechanism

Metal leaks out of the mold during or immediately after casting

Description

Defect Type

Negative

Appearance

Smooth in most instances, but also be rough. It could be irregular. Many features or runners missing because of lack of metal. May have a positive fin where the leaker occurred.

Typical Location

Top of casting as oriented during casting

Aliases

Runout,
Short Pour

Method for defect determination

Visual inspection

| Area | Possible Cause | Potential Correction |
|---------|--|---|
| Wax | Handling damage | Examine process and add preventive measures |
| Shell | Broken shell – handling damage. | Improve dewaxing performance or dip molds after dewaxing, mold handling to prevent damage to the mold |
| Shell | Low mold strength | Verify slurry in spec and control or add shell layers |
| Shell | Dewax cracking | Fill mold with colored dye/water mix to identify crack locations. Add wax vents. Improve dewaxing performance |
| Shell | Poor patch coverage— incomplete drying | Modify patching procedure to insure complete drying prior to placing in burnout oven |
| Shell | Handling damage | Examine process and add preventive measures |
| Foundry | Rough handling of hot mold | Examine process and add preventive measures |
| Foundry | Handling damage | Examine process and add preventive measures |

Non Fill



Mechanism

During casting, the metal freezes before mold cavity is completely filled out

Description

Defect Type
Negative

Appearance

Incomplete casting with rounded edges where casting is not completely formed

Typical Location

Thin sections and sharp edges away from the gate

Similar to

[Cold Shut](#), Wax non fill (See Atlas of Wax Pattern Defects)

Aliases


Misrun

Method for defect determination

Visual Inspection

| Area | Possible Cause | Potential Correction |
|---------|-------------------------------|--|
| Shell | Low mold permeability | Increase shell permeability. Consider reducing shell thickness. Vent thin sections |
| Foundry | Low metal pouring temperature | Increase metal temperature, improve ladle preheating, speed time from tap to pour |
| Foundry | Low mold temperature | Speed time from oven to cast or insulate mold to prevent heat loss |
| Foundry | Interrupted pour. | Pour without interruption |
| Foundry | Lack of metal fluidity | Increase fluidity by reducing metal oxides or adjustment of the metal chemistry |
| Foundry | Poor gating system | Modify gating design to create more entry points for alloy |

Non-Metallic Inclusion



Mechanism

Foreign material in the mold cavity which can originate either from the mold or from outside the mold. The shape of the defect aids in determination of the source

Description

Defect Type
Negative

Appearance

Generally a smooth sided irregular negative shape of indefinite size. Inclusions caused by ceramic material are usually more angular and may contain bits of embedded ceramic.

Size

Variable

Typical Location

Most obvious on external surface of casting where the “inclusion” prevented the alloy from filling the mold cavity to the shell surface.

Aliases

Dirt, Ash

Method for defect determination

Visual Inspection

| Area | Possible Cause | Potential Correction |
|-------|---|---|
| Wax | Junction between wax gate and sprue not completely sealed (undercuts). Ceramic fills the undercut during shelling and breaks off during dewax or pouring. | Improve gating technique to eliminate undercuts. Make sure wax joints (parts to sprue) are smooth and complete. |
| Wax | Filter breakage | |
| Wax | Ash in wax – as in wax typically floats in the molten alloy and is present on the top-side of castings | Test ash content of wax |
| Wax | Incomplete soluble removal | Confirm soluble leaching process and inspection is adequate |
| Wax | Filler settles out in areas that do not drain during dewaxing | Reconfigure gating design to improve wax removal. Add wax bleeder |
| Shell | Cracks in mold and ceramic bits get into mold cavity | See Finning |


continued on next page

Non-Metallic Inclusion



continued from previous page

| Area | Cause | Potential Correction |
|-------------|---|--|
| Shell | Poor mold patching technique – patch enters mold | Improve patch technique |
| Shell | Poor adhesion of shell layers to one another | See Spall |
| Shell | Ceramic debris entering mold after dewaxing (poor housekeeping) | Cover the pour cup after dewaxing (allow moisture from the mold to escape). Store the mold cup down. Wipe rim of pour cup before turning up-right |
| Shell | Ceramic breaking loose inside the mold during dewaxing | Vacuum or wash out mold after dewaxing |
| Shell | Slurry floods pour cup during shell building | Cover pour cup, immediately rinse slurry out. Remove all dried ceramic prior to dewaxing. Coat the inside of the pour cup with wax prior to shelling to aid in slurry removal from cup during dewax. |
| Shell | Ceramic material from jagged lip/edges on in house shell built pouring cups is broken off during handling, burnout or casting | Use a preformed ceramic pour cup or assure in house shelled cup is uniform and robust on top edge |



Mechanism

The blasting media used in mechanical cleaning equipment is typically harder than the casting. The surface of the casting can be deformed or eroded by extended blasting time or excessive blasting energy.

Description

Defect Type
Negative

Appearance


Small negatives possibly with accompanying burrs. Textured surface. May have rolled edges. Eroded features

Typical Location

Surfaces exposed to shot or sand blast media

Aliases

Blasting damage



| Area | Possible Cause | Potential Correction |
|-------|---|---|
| Other | The casting are too hot during blasting | Allow parts to cool prior to blasting |
| Other | Castings are stopped in front of the blasting nozzle or wheel | Insure the parts are constantly moving during the blasting cycle. Check the mill or spinners to confirm movement during the blast cycle |
| Other | Blast time is too long | Reduce blast time |
| Other | Blast media is too large | Reduce blast media size |
| Other | Blast media is too hard | Use softer blast media |



Mechanism

During casting a refractory oxide skin is formed in the melt through the exposure of reactive elements to oxygen. Certain elements are more reactive than others and will preferentially oxidize. The metallic oxide that is formed can be aggravated with turbulent filling.

Description

Defect Type
Negative

Appearance
Metallic oxides are thin black sub-surface streamers forming an irregular pattern or agglomeration on the surface of the casting.

Special Circumstances
More commonly encountered with alloys containing highly reactive elements (Ti, Al, Zr, Cr, etc.)


Size
Varies

Typical Location
Surface and subsurface

Similar to
[Rat-tailing](#), [Cold shut](#), [Slag](#)



Aliases
Oxide Folds, Dross, [Slag](#), Oxide Film

Method for defect determination
Metallic oxide indications tend to be thin, irregular, randomly placed or located, strings of materials containing oxygen and reactive elements. Metallic oxide indications can be determined by visual or EDS inspection.



| Area | Possible Cause | Potential Correction |
|---------|--------------------------------|--|
| Foundry | Impure melting stock | Use oxide-free melting stock or filters |
| Foundry | Oxidation of reactive elements | Prevent oxidation of the melt through the use of vacuum or protective atmosphere |
| Foundry | Improper deoxidation practice | Allow time for deoxidation adds to be effective, agitate melt and de-slag for improved deoxidation |
| Foundry | Turbulence | Reduced filling speed |

Penetration



Mechanism

Metal penetrates into the primary layer during casting. Pinholes or air pockets in the primary layer fill with metal during casting

OR

Stucco penetrates the primary surface and traps an air pocket against the wax

Description

Defect Type

Positive

Appearance

Small discrete positives which appear like grains of sand. When severe, the positives are closely clustered and the surface feels like sandpaper

Typical Location

Near gates, heavy sections or slow to cool sections of the casting

Aliases

Burn-in, burn on, pimpling, stucco penetration, rough surface

Method for defect determination

Visual inspection

| Area | Possible Cause | Potential Correction |
|-------|---|--|
| Shell | Stucco particles too large | Change shell code, use finer stucco on the first few shell layers |
| Shell | Incomplete slurry mixing | Insure the slurry is completely mixed before using in production |
| Shell | Foaming in slurry | Insure air is not being sucked into the slurry by the mixer. Conduct antifoam test and adjust if necessary |
| Shell | Primary slurry instability (micro-gelling) refractory solids) | Conduct gel test on binder solution. Replace slurry if bad |
| Shell | Prime slurry layer too thin | Increase slurry viscosity or reduce slurry drain time. Modify drain orientation. Double dip the mold in the slurry. Increase the pre-wet drain time or orientation |
| Shell | Reaction with primary coat contaminants | Ensure rusting or corrosion of the mixing equipment is not occurring. Remove iron contamination with magnets |

continued on next page



continued from previous page

| Area | Cause | Potential Correction |
|-------------|--|--|
| Shell | Drain time too long before stucco application | Optimize drain time. Train operators or adjust robot program |
| Shell | Rainfall sander too high above pattern | Raise pattern in relation to sand fall |
| Shell | Non-uniform sand delivery from rain rainfall equipment | Maintain or adjust equipment |
| Shell | Improper air flow in fluid bed | Reduce air flow as needed, keep bed clean. Maintain sufficient flow to avoid having to force patterns into bed |
| Foundry | High ferrostatic pressure | Reduce the height of the mold. Reduce the vacuum level. Reduce the spinning speed (centrifugal casting) |
| Foundry | Casting cooling rate too slow | Speed up casting cooling, insure cast molds are not too close together. If penetration localized to hot spots, improve radiant heat loss by lengthening gates or increasing the spacing between adjacent parts |
| Foundry | Oxidized metal | Improve melting and casting process to prevent oxidation of the melt |
| Foundry | Metal temperature too hot | Reduce metal temperature |

Pinholes




Mechanism

Gases are absorbed in metal during melting. If the gas level in the melt exceeds the solid state solubility limit, bubbles are formed during solidification. The gases most responsible for this defect are hydrogen and nitrogen.

Alternate Mechanism

Chemically combined water in the mold is released by the increase in mold temperature during casting.



Description

Defect Type

Negative

Appearance

1/8" or less

Size

1/8" or less

Typical Location

Dispersed throughout the casting but may be more severe in areas that are last to freeze

Similar to

[Gas](#), [Slag](#), [Incomplete Burn-out](#)

Aliases

Metallurgical gas

Method for defect determination

Pinhole defects are typically smaller with a higher frequency than gas, slag or incomplete burn-out. This defect is more common in plain carbon and low alloy steels than in higher alloy steels.

| Area | Possible Cause | Potential Correction |
|---------|--|--|
| Shell | Chemically combined water in the mold released during casting | Dry the molds completely after autoclave dewaxing. Increase the mold preheat temperature. |
| Foundry | High nitrogen, oxygen or hydrogen level in the melt | Use more virgin metal or purchase metal with lower gas content |
| Foundry | Dirty, wet or rusty metal | Metal should be clean, dry and free from rust and oils |
| Foundry | Wet ladles or pouring spouts | Insure complete heating and dry out of furnace pour spouts and ladles |
| Foundry | Incomplete degassing | Confirm degassing additions are correct |
| Foundry | High nitrogen, oxygen or hydrogen level absorption in the melt | Reduce the casting temperature or time the metal is molten. Use a protective or inert atmosphere around melt |

Pitting



Mechanism

Oxygen reacts with chrome in the metal immediately after casting

Description

Defect Type
Negative

Appearance

A multiplicity of dark colored shallow depressions covering a large portion of the casting

Special Circumstances

Can only occur in high chrome alloys such as 400 series and PH stainless steels

Typical Location

Thick, slow to cool sections

Similar to

[Gas](#), [Incomplete Burn-out](#), [Slag](#)

Aliases



Chrome Oxide Pitting, Fusion Spot, Measles

Method for defect determination

Alloy, number of defect sites, depth of defect

| Area | Possible Cause | Potential Correction |
|---------|--|--|
| Foundry | Surface oxidation of high chrome-iron alloys | Ensure reducing or inert conditions immediately after casting. Cover the molds after casting. Use carbonaceous materials in or around the mold. Cool in vacuum or protective or inert atmosphere |
| Foundry | Lack of carbonaceous material in mold | Reduce mold burnout time or add additional carbon layers during shell building |
| Foundry | Casting cooling rate too slow | Increase casting cooling rate |





Mechanism

During shell building, the primary coat cracks and lifts off the pattern. Subsequent slurry layers penetrate and fill the gap between the pattern and the primary coat. This defect is a close cousin to buckle

Description

Defect Type
Positive

Appearance

Island of surplus metal often associated with flash at the casting edge. The edge of the defect has the appearance of a coastline

Typical Location

Sharp corners adjacent to flat or featureless surfaces

Similar to

[Buckle](#)

Aliases


Primary coat buckle, investment penetration

Method for defect determination

With prime coat lift, the shell also fractures, allowing the backup layers to fill the gap between the primary layer and the wax pattern. When a shell buckles, it only separates from the pattern.

| Area | Possible Cause | Potential Correction |
|-------|--|---|
| Wax | Wax pattern temperature not stable | Ensure the wax pattern has stabilized in temperature before applying shell layers |
| Shell | Poor adhesion of the prime coat to the wax pattern | Increase the etch strength or etch time. Reduce the time from etch to 1st layer application |
| Shell | Large temperature drop when applying 2nd layer | Increase the room humidity |
| Shell | Large temperature variation during prime coat drying | Maintain +/- 3 F in the dipping and drying area |
| Shell | Drying too long | Shorten the dry time |
| Shell | Drying too fast (large pattern shrinkage) | Increase the room humidity or reduce airflow |
| Shell | Primary coat binder is gelled | Test the primary coat binder to determine if it is gelled |
| Shell | Uneven primary coating thickness giving rise to variable rates of drying | Modify the draining technique to produce a more uniform slurry coverage |
| Shell | Slurry dry out on sharp edges | Shorten the draining time, increase the humidity in the shell dipping area |
| Shell | Poor adhesion and elasticity properties of the primary slurry | Green strength additives in the primary slurry becoming unstable or ineffective |

Rat-tailing



Mechanism

This defect is a marriage of pitting and finning defects. Rat-tailing is the selective oxidation of the metal surface through cracks or micro-cracks in the shell. Most of the cracks are large enough to be filled with metal during pouring and will produce positive metal fins. Very fine micro-cracks are too small to allow metal to enter, but will allow air (oxygen) to reach the hot casting surface.

Description

Defect Type

Negative with the possibility of positive finning

Appearance

Shallow rounded threadlike fissures typically in a radial pattern

Aliases

Mud cracks, drying cracks, oxidation crazing, rivering

Method for defect determination

Thin, negative defect typically found in high chrome alloys

| Area | Possible Cause | Potential Correction |
|-----------------|---|--|
| Other (Set-up) | Lack of stress raisers on the cast surfaces or in the primary coat refractories | Break-up large flat surfaces on the casting with "hatching" or small ribs which can subsequently be ground off |
| Shell | Large temperature variation during prime coat drying | Maintain +/- 3F in the drying area |
| Shell | Drying too fast (large pattern shrinkage) | Casting cooling rate too slow. Increase dipping and drying room humidity, reduce air flow |
| Shell | Mismatch in expansion coefficient between prime and backup coats | Use slurry and stucco refractories with similar thermal expansion rates |
| Shell | Drying too long | Reduce dry time. cooling rate too slow |
| Shell | Low prime coat strength | Check binder healthy/stability through pH, conductivity and/ or gel test |
| Shell | Low prime coat strength | Increase refractory solids |

continued on next page



continued from previous page

| Area | Cause | Potential Correction |
|-------------|---|---|
| Shell | Poor adhesion and elasticity properties of the primary slurry | Green strength additives in the primary slurry becoming unstable or ineffective |
| Shell | Uneven shell build on prime coat(s) | Evaluate dipping/draining sequence to ensure uniform draining and/or shell build |
| Shell | Permeability of shell is too high | Compare permeability of shell against previous data. If changed, evaluate potential causes for increase |
| Foundry | Oxygen level too high during casting cooling | Ensure reducing or inert conditions immediately after casting. Cover the molds after casting. Use carbonaceous materials in or around the mold. Cool in vacuum or protective atmosphere |
| Foundry | Oxygen level too high during casting. Casting cooling rate too slow | Casting speed cooling rate too slow |
| Foundry | High shell temperature and excessive time in oven | Explore potential ways to reduce shell pre-heat temperature or time |



Mechanism

During casting, droplets of metal detach or are separated from the pouring stream by excessive turbulence, mold design, or metal pouring height. The metal droplet becomes either cooler in temperature or coated with a tenacious oxide film and retains this identity as part of the cast metal.

Description

Defect Type

Negative

Appearance

These are closely related to oxide fold defects but are typically circular in form rather than linear

Size

Can be small up to an inch or more in diameter

Typical Location

Generally located on the surface of the casting

Similar to

Wax flow lines (See Atlas of Wax Pattern Defects)

Aliases

Oxidized droplet

Method for defect determination

Visual or Fluorescent Penetrant Inspection

| Area | Possible Cause | Potential Correction |
|---------------------|------------------------|---|
| Wax | Cold wax at nozzle tip | Wax cold shot can occur in the wax pattern and be duplicated through the shelling process, thereby resulting in a similar-looking metal defect. (Ensure nozzle tip temperature is adequate to keep wax from solidifying). |
| Other (Mold design) | Bad mold design | Mold design should promote non-turbulent metal flow |
| Foundry | Bad pouring practice | Avoid metal splashing during pouring |
| Foundry | Bad pouring practice | Reducing the distance between the crucible and the mold to be poured to minimum, thereby reducing the chance for splashing |
| Foundry | Pouring practice | Employ use of a reticulated foam filter to achieve a laminar flow |
| Foundry | Pouring practice | Formation of a well in the mold to allow the metal to collect and then flow into the mold parts |

Shrink - Gate



Mechanism

The molten alloy shrinks as it solidifies. Inadequate feed metal from the gating system is available to prevent a cavity from forming.

Description

Defect Type

Negative

Appearance

Internal irregular cavity exhibiting an open or porous coarsely crystalline or dendritic structure usually exposed upon removal of the gate. This defect is frequently discovered by caustic salt bleed out from the cavity

Typical Location

Center of gates

Similar to

[Shrink - Surface](#), [Shrink - Internal](#)

Method for defect determination

Visual inspection,
Penetrant Inspection

| Area | Possible Cause | Potential Correction |
|------------------------|----------------------------------|--|
| Other (Gating design) | Gates are too small or too long | Increase height of mold to increase ferrostatic pressure or the gate modulus, consider tapering the gate |
| Other (Casting design) | Low metal pressure | Insulate, hot top or use exothermic material to prevent the pour cup from freezing too early |
| Foundry | Runner system freezing too early | Use selective insulation to promote progressive solidification |
| Foundry | Gates are too small or too long | Increase height of mold to increase ferrostatic pressure or the gate modulus, consider tapering the gate |

Shrink - Internal



Mechanism

Molten alloys shrink as they solidify. As solidification progresses and the solid to liquid fraction increases, it becomes more difficult for liquid feed metal to reach the solidification front. Shrinkage occurs between dendritic arms. In larger defects, inadequate feed metal is provided to isolated hot spots in the casting.

Description

Defect Type

Negative

Appearance

Internal irregular cavities ranging from small dispersed or linear type cavities up to large cavities

Special Circumstances

The occurrence and severity of this defect may be alloy dependent. Alloys with longer (larger) freezing ranges are more prone to this defect.

Size

Shrinkage cavities can range in size from very small (requiring magnification) to very large

Typical Location

Casting centerline between gates or in isolated heavy sections. Areas with sharp internal corners

continued on next page

| Area | Possible Cause | Potential Correction |
|---------------------|---------------------------------|---|
| Other (Mold design) | Inadequate or incorrect feeding | Ensure adequate feeding of the area concerned to promote progressive solidification |
| Other (Mold design) | Incorrect solidification rate | Modify the casting design to promote progressive solidification |
| Other (Mold design) | Vacuum in blind riser | Ensure the v-notch in the riser prevents a vacuum from forming |
| Other (Mold design) | Blind riser too small | Ensure the riser has adequate metal volume |
| Other (Mold design) | Low ferrostic head pressure | Increase the height of the mold. Use centrifugal force to increase head pressure |
| Other (Mold design) | Incorrect solidification rate | Examine the molding technique. Modify the casting design to promote progressive solidification. |
| Foundry | Incorrect casting conditions | Establish the correct casting conditions |

continued on next page

Shrink - Internal



continued from previous page

Similar to
[Shrink - Gate](#), [Shrink - Surface](#)

Aliases
Dendritic shrink, micro-shrink

Method for defect determination
Because this is a subsurface defect, it may not be discovered without x-ray examination, machining or sectioning through the casting.

continued from previous page

| Area | Cause | Potential Correction |
|----------------------------|--|--|
| Foundry | Incorrect solidification rate | Use insulation on specific areas of the mold to increase thermal gradient |
| Foundry | Low metal temperature | Increasing the metal temperature can improve the feeding distance |
| Foundry | Low mold temperature | Increasing the mold temperature can improve feeding distance |
| Foundry | Vacuum created in the feeding system during solidification | Ensure the metal in the head (pour cup) remains liquid longer than the casting. Insulate or use exothermic material on the pour cup and risers |
| Foundry | Dissolved gas level too high | Use a heat makeup and melting practice that produce low dissolved gases |
| Other (Casting Processing) | Inadequate or incorrect feeding | Use hot isostatic pressing (HIP) to close up the defects. Cap weld all surface connected shrinkage prior to HIP. |

Shrink - Surface



Mechanism

The molten alloy shrinks as it solidifies. Sharp inside corners thermally saturate the shell and cool slower than the surrounding area. Unfavorable thermal geometry resulting in an isolated liquid metal heat center. The shrinkage of the internal section, cut off from supplies of further liquid feed metal, causes atmospheric pressure to collapse the adjacent skin where the metal is still sufficiently hot and weak to do so.

Description

Defect Type
Negative

Appearance

Surface depression or irregular cavities exhibiting an open or porous or coarsely crystalline structure sometimes exhibiting a dendritic appearance. These defects are frequently discovered by caustic salt bleeding out of the cavity after the leaching.

Typical Location

Fillets, sharp intersections. or slow and are commonly found at corners of castings near the ingate

Similar to

[Shrink - Gate](#), [Shrink - Internal](#)

Aliases


Hot spot porosity

Method for defect determination

Visual and Penetrant inspection

December 2017

| Area | Possible Cause | Potential Correction |
|----------------------------|--|---|
| Wax | Fillet too small | Increase fillet size |
| Wax | Inadequate feeding. Castings too close together – localized mold hot spots | Ensure adequate feeding. Improve pattern spacing and avoid refractory build-up in completing molds. |
| Foundry | Metal pouring temperature too hot | Consider reducing temperature |
| Foundry | Mold temperature too hot | Consider reducing temperature |
| Other (Metal/ Mold design) | Differences in radiant cooling. | Review the assembled mold. Is the defect related to a specific position on the mold? |
| Other (Casting design) | Fillet too small | Increase fillet size |
| Other (Mold design) | Inadequate feeding. Castings too close together – localized mold hot spots | Ensure adequate feeding. Improve pattern spacing and avoid refractory build-up in completing molds. |



Mechanism

Heavy section of wax pattern shrinks as it cools. The vacuum created during cooling causes the surface to cavitate or dish inward.

Description

Defect Type
Negative

Appearance
Smooth, dished surface depression

Size
varies



Typical Location
Heavy sections or thick flat surfaces

Similar to
Wax Shrink (See Atlas of Wax Pattern Defects)

Aliases
Cavitation

Method for defect determination
Visual inspection, overlay of straight edge or customary dimensional inspection tools

| Area | Possible Cause | Potential Correction |
|-------------------------|------------------------------------|--|
| Other (Wax Tool Design) | Feed runner freezing prematurely | Increase size or add runner to affected section |
| Wax | Incorrect wax injection parameters | Reduce wax temperature, increase injection time, increase injection pressure |
| Wax | Missing wax chill | Create wax chill to reduce the volume of injected wax in the area of sink/cavitation |
| Wax | Hot wax chill | Allow time for the wax chill to cool to room temperature before inserting in the wax injection die |



Mechanism

During melting or casting, slag is produced as a function of time, temperature and availability of oxygen. This slag is mixed with the metal during pouring and, being less dense than the metal, floats to the top surface of the casting.

Description

Defect Type

Negative

Appearance

A series of smooth-walled symmetrical surface cavities with or without traces of dark glassy included material

Typical Location

Top surface of the casting as oriented at casting

Similar to

[Gas](#), [Pinholes](#), [Incomplete Burn-out](#)

Method for defect determination

It is difficult to visually distinguish between slag and gas defects. The defect shapes are similar as is the location. Inspection of the defect under magnification may reveal residual slag.

| Area | Possible Cause | Potential Correction |
|---------|--|--|
| Shell | Metal / mold reaction | Cast at the lowest possible mold and metal temperature. Increase the refractoriness of the primary coat |
| Foundry | Crucible / metal reaction | Employ correct crucible and melting practice |
| Foundry | Oxidation of furnace lining or ladle | Change to more refractory material |
| Foundry | Poor or improper deslagging practice | Ensure adequate slag removal at lowest possible temperature. Allow time for slag in melt to float out. Remove slag. Use slag coagulants if necessary to improve removal. |
| Foundry | Excessive superheat temperature and or holding times | Minimize the time the metal is at temperature |
| Foundry | Oxidation of metal during melting | Consider protecting the melt using inert gas |
| Foundry | Silicates formed during deoxidation | Modify the deoxidation practice |



continued on next page



continued from previous page

| Area | Cause | Potential Correction |
|-------------|---|--|
| Foundry | Slag from the ladle entering the mold | Use ceramic or cloth filter |
| Foundry | Slag from ladle entering the mold | Consider using a bottom pour (teapot) ladle |
| Foundry | Turbulent pouring conditions - metal poured from great height above molds | Minimize the distance from the furnace / ladle to the mold |

Slurry Leakage



Mechanism

Liquid ceramic slurry enters the mold and dries creating a positive in the mold that is represented as a negative in the casting

Description

Defect Type
Negative

Appearance
Shallow, irregular depression in casting surface


Size
varies

Typical Location
Near wax vent or in mold crack

Method for defect determination
Visual inspection

| Area | Possible Cause | Potential Correction |
|--------------------------|--|-----------------------|
| Shell | Damage to coating creates separation from wax passage for slurry entry | Awareness/Handling |
| Other (Mold Preparation) | Inadvertent spill | Awareness/Cleanliness |

Spall



Mechanism

The layer to layer bond in the shell construction is not strong enough and the ceramic fractures off the mold surface during dewaxing, mold preheating or casting and falls into the mold cavity

Description

Defect Type

Positive (with corresponding negative)

Appearance

Sharp or irregular positive defect normally accompanied by a negative defect (inclusion) from the ceramic that has “spalled” off and appears somewhere else on the casting.

Typical Location

Detailed areas such as depressed lettering, score lines, teeth, tight slots, fillets or sharp corners

Similar to

[Penetration](#) (positive),
[Non-Metallic Inclusions](#) (negative)

Aliases

Spalling, prime coat spall, pre-coat spall, undercuts

Method for defect determination

Visual Inspection

| Area | Possible Cause | Potential Correction |
|-------|--|--|
| Shell | Excessive 1st layer slurry that results in weak inter layer shell construction | Fully drain slurry coats |
| Shell | Incomplete 1st layer dry that results in weak inter layer shell construction | Extend prime slurry dry time |
| Shell | Excessive pre-wet that results in weak inter layer shell construction | Fully drain pre-wet to matte finish |
| Shell | Prime coat stucco too fine that results in weak inter layer shell construction | Skim fines/dust from the fluid bed or screen out, use coarser stucco |
| Shell | Low primary slurry binder level | Check SiO ₂ level of primary slurry |
| Shell | Prime slurry binder gelling | Conduct gel test on primary slurry binder |



continued on next page

Spall



continued from previous page

| Area | Cause | Potential Correction |
|-------------|-----------------------------|--|
| Shell | Poor stucco adhesion | Insure the slurry is not drying before stucco, eliminate stucco rub off, blow off loose stucco |
| Shell | Prime coat slurry too thick | Reduce prime coat viscosity |
| Shell | Etch too strong | Reduce etch time, etch strength or increase time from etch to 1st layer application |
| Shell | Thermal expansion mismatch | Use refractories that have similar thermal expansion characteristics |



Stuck Shot



Mechanism

Shot wedged into lettering or detailed areas during shot blasting operation

Description

Defect Type
Positive

Appearance
Smooth - round, oval, or hemispherical

Special Circumstances
Can only occur in areas of the casting that shot can get wedged into

Size
1/8" or less

Typical Location
Highly detailed areas such as depressed lettering or score lines

Similar to
Wax bubbles (See Atlas of Wax Pattern Defects), [Bubbles](#)


Aliases
Positive metal

Method for defect determination
Stuck shot can be pried out. Can also section, mount and polish through defect. Stuck shot will not be attached to the casting – only wedged in place



| Area | Possible Cause | Potential Correction |
|--------------------|-------------------------------------|----------------------|
| Other (Shot blast) | Shot is the wrong size for the part | Change the shot size |

Wax Drip



Mechanism

Molten Wax or sticky wax drips onto the pattern during gating assembly process

Description

Defect Type

Positive

Appearance

Smooth. Spherical or oval shaped sometimes accompanied with a tail.

Typical Location

Exposed surface during gating

Aliases

Wax Splatter

Method for defect determination

visual

| Area | Possible Cause | Potential Correction |
|------|----------------------------------|---|
| Wax | Wax melting iron / torch too hot | Reduce temperature |
| Wax | Sticky wax too hot | Reduce to correct temperature |
| Wax | Poor gating technique | Use a shield (aluminum foil) to prevent drips from getting on the pattern |



List of Defects

Bubbles 8
Buckle 9
Bulge 11
Chill Breakout *
Cold Shut 13
Core Breakage 14
Crack 15
Cut-off Damage 17
Delamination 18
Distortion 20
Etch Spotting 22
Excess Metal 23
Finning 25
Gas 27
Grinding Damage 29
Handling Damage 30
Hot Tear 31
Incomplete Burn-out 33
Leaker 34
Non Fill 35
Non-Metallic Inclusion 36
Overblast 38
Oxide 39
Penetration 40
Pinholes 42
Pitting 43
Prime Coat Lift 44
Rat-tailing 45
Shot Defect 47
Shrink - Gate 48
Shrink - Internal 49
Shrink - Surface 51
Sink 52
Slag 53
Slurry Leakage 55
Spall 56
Stuck Shot 58
Wax Bubbles *
Wax Crack *
Wax in Die *
Wax Drip 59
Wax Flash *
Wax Flowlines *
Wax Knitlines *
Wax Non Fill *
Wax Splatter *

Aliases

Bubbles

BBs
Air bubble

Bulge

Bulging
Bulging cracking
Bulging overheating
Shell bulge

Cold Shut

Cold shot
Short fill

Delamination

Scabbing
Reverse buckle

Etch Spotting

Fisheyes

Excess Metal

Metal breakthrough
Metal penetration
Core collapse

Finning

Flash
Shell crack
Mold crack

Gas

Entrapped air
Porosity

Handling Damage

Knockout Damage

Hot Tear

Shrinkage crack

Leaker

Runout
Short pour

Non-metallic Inclusions

Dirt
Ash

Non Fill

Misrun
Cold shut

Overblast

Blasting Damage

Oxides

Misrun
Cold shut
Oxide folds
Dross
Oxide film

Penetration

Burn-in
Burn-on
Pimpling
Stucco penetration
Rough surface

Pinholes

Metallurgical gas

Pitting

Chrome oxide pitting
Fusion spot
Measles

Prime Coat Lift

Primary coat buckle
Investment penetration

Rat Tailing

Mud cracks
Drying cracks
Oxidation crazing
Rivering

Shot Defect

Oxidized droplet

Shrink – Internal

Micro-shrink
Dendritic shrink

Shrink – Surface

Hot spot porosity

Sink

Cavitation

Spall

Spalling
Prime coat spall
Pre-coat spall
Undercuts

Stuck Shot

Positive metal

Wax Drip

Wax Splatter

* See ICI Atlas of Wax Pattern Defects



Other ICI publications

Atlas of Wax Pattern Defects, REVISED 2ND Edition

A listing of probable cause effect relationships with the variables relating to the wax pattern area. Such problems as sink; cavitation; shrink; pattern crack; chill damage; air bubbles; flash; pattern distortion are examined. This atlas can be used as a new learning tool, a stimulating refresher for the more experienced caster, or as a tool for brain-storming a discovered defect. 2003, Investment Casting Institute.

Ceramics Testing Guidebook

Prepared by the Ceramics Committee of the Investment Casting Institute this book contains technical information on refractories and chemical materials used in investment casting, as well as testing procedures for refractory materials, colloidal silica binders, ethyl silicate binders and miscellaneous chemicals. Also includes testing procedures for solid mold materials, slurries and shells, ceramic cores and shapes. This and the ceramic video training series are a must for every investment casting operation! Revised 2005.

Finishing Operations

Finishing Operations covers robotic deburring and polishing, abrasive cut-off wheels, economics of friction sawing investment castings, rapid grinding gate removal abrasive sandblasting media, the basics of blast cleaning, gate and sprue removal with belts, final part finishing, air grinding tools, portable wheels and mounted points, carbide burs, and hot straightening of investment casting. 1989, Investment Casting Institute.

Fundamentals of SPC

Details principles of process and cost improvement, data collection, statistics and methodology while demonstrating data plotting and interpretation. Many case studies and examples. A top notch presentation by the Investment Casting Institute.

How to Avoid Shell Cracking: A Symposium

Based on an Investment Casting Institute training symposium, this book contains 13 papers from experts throughout the industry with practical information on how to avoid shell cracking. Papers cover the gamut: design, wax properties, raw materials, slurry control, environmental conditions in drying, autoclave, dewaxing, and handling. 1989, Investment Casting Institute.

Investment Casting 101 Booklet

Investment Casting 101 is a compact booklet providing a brief look at the basics of the investment casting process and how it works, an overview of the benefits of investment casting, why and when it makes sense, and dozens of pictures illustrating various applications. This is a great marketing tool priced low enough that investment casters can send it or give to all their potential customers.

Investment Casting Case Studies and Applications Published 2014 - Set of 20

The Investment Casting Case Studies and Applications supplement, which appeared in the August issue of INCAST, is now available as a marketing tool to Investment Casters. The 28-page, full-color booklet illustrates scores of investment casting applications in aerospace, industrial gas turbine, medical, automotive, military, sports/recreation and commercial/industrial markets. Many photos are accompanied by case studies which explain why investment casting was the preferred manufacturing process. The new publication clearly shows the flexibility and benefits of the investment casting process and since company names are not used, it is the process rather than the individual caster which is promoted.

Investment Casting Handbook

Put this resource in the hands of your potential customers! An excellent tool for designers, buyers and users of investment castings, as well as for employees in the investment casting foundry. Contains chapters on the following: 1). The Investment Casting Process; 2). How to Buy Investment Castings; 3). Dimensions, Tolerances, and Surface Texture; 4). Designs and Applications of Investment Casting; 5). Quality, Evaluation, Inspection and Control; 6). Alloy Selection. Plus numerous case studies, examples and dozens of full-color illustrations. 1997, Investment Casting Institute, 123 pp., illus.

Metal Standards and Specifications for Investment Castings

Metal Standards and Specifications for Investment Castings defines a typical level of metal quality by the industry as a service to purchasers of investment castings who do not cite detailed specifications. This includes a list of the most common investment casting alloys, chemistries and typical mechanical properties. A revision of the old standby Metal Quality Standards, the new book is intended as a handy reference guide not only for foundries, but also for end users.

For more information about ICI's other publications please visit: www.investmentcasting.org.